Exchange Building • 821 Second Ave. • Seattle, WA 98104-1598

October 11, 1990

James C. Brown ALASKAN COPPER WORKS Box 3546 SEATTLE, WA 98124

Dear James C. Brown:

Enclosed are the analyses from Metro's most recent effluent sampling at your facility for our Heavy Metals Control Program. All values met Metro's discharge limits.

Metro appreciates your good compliance. If you have any questions, please call your Metro contact person: Christie True 684-2327; Bruce Burrow 684-2329; Ray Carveth 684-2336 Doug Hilderbrand 684-2341; Denise Healy 684-2328; Michelle Dewey 684-2368; Jim Sifford 684-2335; Jacqueline Eden 684-2378; or Louise Kulzer at 684-2373.

Very truly yours,

Industrial Waste Investigator Comprehensive Planning Division

Enclosure

DESCRIPTION		STATION		SITE	
ALASKAN COPPER	ASKAN COPPER WORKS		A4010		SOUTH
	DATE  900928	TIME  1150	TYPE  G	ID  95	531
- SILVER - ARSENIC CADMIUM CHROMIUM COPPER NICKEL LEAD ZINC PH	AG AS CD CR CU NI PB ZN PH	< 0 < 0 < 0 < 1 0 0 < 0	mg/1)  .0030 .0500 .0020 .3000 .8500 .8100 .0300 .0760		LBS

**KEY** 

PH is in standard units.

## TYPE

G

Grab sample.
Series hourly sample representing 2 hours.
Composite sample representing 24 hours.
Composite sample based on flow. SH02

CH24

CH00

## **VIOLATIONS**

#\*

Exceeded limits but not legal violation.
Legal violation subject to enforcement action.
Legal violation - Slug violation.
Concentrated discharge exceeding discharge limits by a factor of 10. Legal violation. SLUG